



2007 NGK Rally of Melbourne - VRC

Retirements



Listed By Vehicle No

Veh	Heat	Reason
17	1	SS4 Rolled
17	2	Did Not Start Heat 2
19	1	SS2 Off road
21	1	SS8 Hit tree
21	2	Did Not Start Heat 2
25	1	SS4 Off road
25	2	Did Not Start Heat 2
29	2	SS11 Head gasket
30	1	SS4 Blown Turbo
31	2	Did Not Start Heat 2
38	1	TC2 Withdrawn
39	1	SR1 Off Road
39	2	SS11 Gearbox
40	1	TC5C Exhaust broken
43	1	TC9 Flat tyres
46	2	SS16 start Oil Leak
48	1	SS2 Fire
48	2	Did Not Start Heat 2
50	1	TC2 Overheating
50	2	SS14 Gearbox
51	2	SS12 Hit bank